Idaho PUC Pipeline Safety Inspection Summary

nspector(s): Perkins				Date(s):	30 Jun-1 Jul 20
Company/Owner:	Intermo	untain Gas Company	U	nit/OPID:	8160
					et
Inspection Type & Time (1	day)		Total Insp	ection Days:	1
Standard: Construction:	2 Training:] (T)(D) Integrity Mar	nagement:	Incident:	
M/M: Follow-up:	OQ:	Damage Preve	ntion:	D&A:	
Inspection Summary					
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.					
30 June-1 Jul 2020: (1.0 Const Observed a Das-co crew instal Approximately 600' trench/bo Areas observed during this pro bedding/backfilling. Attachments: IPUC Form 4 Construction Insp Das-co daily Itineraries located OQ's for all observed employed	Il new 6" main east ore. All procedures of oject were: Excavat oections d in file for the proj	were followed. Type ting, line locating, fu	d up report		
Corrective Action Required: Yes No Inspector (Lead): Bruce Perkins Reviewer:		ow-up Required:	D	No y (date): ate: 7/1/2020 ate:	X 2620